

Winterization Checklist

Sample Customer

4700 N 27th St., Tawas City, MI 48763

14/14 Tasks Completed



Mobile RV Tech Services

PO Box 609, East Tawas, MI 48730

Steve Puvalowski

help@mobilervtechservices.com

19898207373

Job Information

✓ Customer & RV

Customer:

Sample Customer

RV:

Open Range 5th Wheel

Generator:

Onan 5,500 - Gas

RV Appliances

Ice Maker

Washing Machine

Dishwasher

N/A



Winterization - Basic Package

✓ Holding Tanks Drained

Fresh Water Tank

Yes

No

N/A

Grey Water Tank(s)

Yes

No

N/A

Notes:

✓ Fresh Water Lines

Inline Water Filter Removed

Yes No N/A

Open Faucets & Low Point Drains

Yes No N/A

Blow Out Supply Water Lines

Yes No N/A

Blow Out Fresh Tank to Pump Line

Yes No N/A

Notes:

The RV will need a set of 3 new water filters in the spring.



✓ RV Antifreeze

Fresh Water Lines

Ice Maker

Yes No N/A

Kitchen Sink

Yes

No

N/A

Bathroom Sink(s)

Yes

No

N/A

Inside Shower(s)

Yes

No

N/A

Toilet(s)

Yes

No

N/A

Washing Machine Connection(s)

Yes

No

N/A

Outdoor Shower/Spray Port(s)

Yes

No

N/A

Outdoor Kitchen Sink

Yes

No

N/A

City Water Inlet Check Valve

Yes

No

N/A


Black Tank Flush Line

Yes

No

N/A

Notes:



Holding Tanks Closed

Fresh Water Tank

Yes No N/A

Grey Water Tank(s)

Yes No N/A

Black Water Tank(s)

Yes No N/A

Notes:

RV Antifreeze

Drain Traps

Sink(s)

Yes No N/A

Shower(s)

Yes No N/A

Toilet(s)

Yes No N/A

Washing Machine Drain

Yes

No

N/A

System Depressurized

Yes

No

N/A

Notes:

Winterization - Plus Package (All the basic items with requested additions)

Batteries

Disconnected

Switch

Negative Cable

No

N/A

Removed for Customer Storage

Yes

No

N/A

Notes:

Service & Flush Tank(s)

Flushed (If has built in flushing system)

Yes

No

N/A

Cables Treated w/WD-40 Dry Lube

Yes

No

N/A

Notes:

Slideout Maintenance

Slideout Sealant Condition

Pass

Fail

N/A

Seal Inspection Condition

Pass

Fail

N/A

Treat Slideout Seals

Yes

No

N/A

Lubricate Gear Tracks

Yes

No

N/A

Slideout Alignment


Acceptable Position

Adjusted to Allow for Proper Sealing

N/A

Notes:

The tops of the slideout seals are starting to rip where the cables go through them.



✓ Roof & Sidewall Sealant Inspection

Roof Material Condition

Pass

Fail

N/A

Roof Sealant Condition

Pass

Fail

Needs Immediate Attention

Needs Future Repair Work

N/A

Sidewall Sealant Condition

Pass

Fail


Needs Immediate Attention

Needs Future Work

N/A

Notes:

There are cracks in the roof sealant by the bathroom vent fan. It is recommended to repair these before winter.



✓ RV Generator

Stabil Added to Fuel Source

Yes

No

N/A


Ran & Exercised for 15 Minutes

Yes

No

N/A

Notes:



Job Completion

Notes

Wrap Up

Keys

Gave back to customer

Put back in hiding spot

Customer opened RV

Still in our possession

Used master key

Parts needed for spring de-winterization:

- Water filters
- Change generator oil

Repairs Needed:

- Roof sealant by bathroom vent
- Slideout seal repair